FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-15-14 Time: -11:00 An Location: 210 Howard Ave
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 1/2 Repaired Under Pressure: YES_VNO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Pin ho/e
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

Rev 01-21-09

the company text and the company text and the company text and the company text are company to the company text and the company text are company to the company text and the company text are company to the company text are company text are company to the company text are compa

the second of the second

에 가는 사람들이 있는 사람들이 없어 없는 사람들이 없어 없었다면 없는 사람들이 없어 없는 사람들이 없는 사람들이 없는 사람들이 없어 없었다면 없는 사람들이 없어 없어 없어 없었다면 없어 없었다면

in the spiral of the second of

그 그리는 사람들이 한 사람들은 경향을 하는 것으로 되는 것이 생각하는 것이 되었다.

20 42