| | THE REAL FOR NEWLINE INCTAIL ATION OF LINE REPAIR |
|---|---|
| | FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR |
| | Date: 7-12-13 Time: 9:30 Location: 218 Heritge Hills |
|) | Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line |
| | NEW LINE INSTALLATION: |
| | Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): $7/22/13/13$ |
| | Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush: |
| | Water Supply (WS) Project Number: |
| | FOR LINE REPAIRS: |
| * | Interruption of Water Service: YES NONumber of CustomersAffected: |
| | Main Size: 4(PUL Repaired Under Pressure: YES NO |
| | For partially or fully de-watered mains: |
| J | Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm |
| | Nature of Leak or Break: Busted Ugcant 4" PUC - Not in Usc |
| | Were State approved or AWWA Standards Followed: (YES/NO) Cut out and Detailed summary of repair procedure used (Use back of page if needed): deplote with |
| | Was water main contaminated during the repair process? (YES / NO) Bleached Knock-ons Disinfection Procedure / Calculations (Use back of page if needed): Flushed line |
| | Amount of Time Line Flushed: 25 Minutes Ending Chlorine Residual: mg/L |
| | Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record) |
| | Date / Time Water Main Returned to Service: am / pm |
| | Additional Comments: Sec Photos Floshed out line then Rev 01-21-09 Adam turned Uslue back Off. |
| | Rev 01-21-09 Adam tuined Value back oft. |
| | T.J. X Line is not in Use |



CORPORT OF A CONTRACT

말하는 것 같아요. 전 것 같아? 것 같아?

- 사람이 한 40 - 이 1987년 이 전에 가죽이 가죽 10 - 10 40 40 - 10 - 10 10 1941

가는 것 같아요. 또 가는 것 것 같아요. 아이들 것 같아요. 이들 것 같 이들 것 같아요. 이들