

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-26-12 Time: 1:00 p.m. Location: 226 Virginia Ave

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

9/28/12

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ✓ Number of Customers Affected: 0

Main Size: 1" Galv Repaired Under Pressure: YES ___ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

pin hole in Galv

Were State approved or AWWA Standards Followed: YES / NO) Repaired with
Detailed summary of repair procedure used (Use back of page if needed): Band

Was water main contaminated during the repair process? (YES / NO) NO
Disinfection Procedure / Calculations (Use back of page if needed): Bleached Band

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES ___ NO ___ Results**: _____
(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

See Photos

8 GPM Leak

Rev. 01-21-09

Adam Bull
Donnie

COPY