

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 11/21/10 Time: 3:00 pm Location: 228 Hassle Mill Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

Date: Time of Initial Flush:

Chlorine Residual after Flush

11/23/10
J

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Repaired Under Pressure: YES NO

Not partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)

Water Main Valved Off (positive pressure removed): am pm

Leak or Break

6" Split

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Bleached Band

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure: Calculations (Use back of page if needed)

Amount of Time Line Flushed:
Residual mg/L

Minutes

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service

20

am pm

Additional Comments

1943