

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-6-12 Time: 10:30 Location: 2313 Swan Pond Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ☒ Number of Customers Affected: _____

Main Size: 3" Trans Repaired Under Pressure: YES ☒ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: _____

Replaced leaking saddle

Were State approved or AWWA Standards Followed (YES / NO) YES

Detailed summary of repair procedure used (Use back of page if needed): Banded old tap and made a new one

Was water main contaminated during the repair process? (YES / NO) NO

Disinfection Procedure / Calculations (Use back of page if needed): Bleached band and saddle

Amount of Time Line Flushed: _____ Minutes

Residual: _____ mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES ___ NO ___

(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: _____

See Photos

Aden-Donnic-Bull-Billy

COPY