

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-4-13 Time: 9:00 PM Location: 272 Harding Rd

Please Circle Appropriate Action: New Line Installation / Line Repair Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

9/6/13 J

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 1

Main Size: 4" Repaired Under Pressure: YES ☒ NO ☐

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Service line had hole in it

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: _____ Minutes
Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐
(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: Photos

Taylor / Donnie / T.J.

CCNY