36

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 7-15-14 Time: _9100 Location: 2833 Airport Rd
Please Circle Appropriate Action: New Line Installation / Line Repail Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Sizè: Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) 1 Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Leaking Service line
Were State approved or AWWA Standards Followed: (YES NO) Replaced with Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO)) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01-21-09 Adam Simmy Billy Simmy

COPY

e de la companya della companya della companya de la companya della companya dell

ji naga

4

destruction of the second

2