	FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
	Date 1-23-13 Time: 2:30 pm. Location: 308 Frost Houfflow Rd
ί.	Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
$\overline{}$	NEW LINE INSTALLATION:
	Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): 1-24-33
	Chlorine Residual Prior to Initial Flush: Length of Time of Initial Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
	Water Supply (WS) Project Number:
	FOR LINE REPAIRS:
	Interruption of Water Service: YESNONumber of CustomersAffected:
	Main Size 2" PUC Repaired Under Pressure: YES NO
	For partially or fully de-watered mains:
U	Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) NO) 'Time Water Main Valved Off (positive pressure removed): am / pm
	Nature of Leak or Break Small picce of plastic leaking
	Were State approved or AWWA Standards Followed: (YES/NO) Replaced with Detailed summary of repair procedure used (Use back of page if needed): (oppic)
	Was water main contaminated during the repair process? (YES NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed):
	Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L
	Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
	Date / Time Water Main Returned to Service: am / pm
\cup	Additional Comments: Sec Photos
	Adam - Bull - Tim
	1 GPM Leak

ે જે કુલ્લા કે મહાવા દિવાળ છે. સામ કે જે કુલ્લા કે મહાવા દિવાળ જેવા છે.