

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-7-14 Time: 3pm Location: 308 Frost Hill

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

## NEW LINE INSTALLATION:

*2"* *Taylor, Jimmy, B. 11/1, TJ.*

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

**COPY**

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES \_\_\_\_ NO ☒ Number of Customers Affected: \_\_\_\_\_

Main Size: 2" PVC Repaired Under Pressure: YES ☒ NO \_\_\_\_

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)  
(NO)

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break:

Crack in pipe

Were State approved or AWWA Standards Followed: (YES) / (NO)

Detailed summary of repair procedure used (Use back of page if needed):

*Dig around & below pipe*

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

*Cleaned material with bleach & put on main.*

Amount of Time Line Flushed: \_\_\_\_\_ Minutes

Ending Chlorine

Residual: \_\_\_\_\_ mg/L

Bacteriological Sample Collected: YES \_\_\_\_ NO \_\_\_\_

Results\*\*: \_\_\_\_\_

(\*\*Attach copy of results to record)

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments:

COPY