

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-17-13 Time: 10:00AM Location: 317 Riggs Chapel

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of disinfection procedure used (Use back of page if needed):

9/18/13

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ____ NO ✓ Number of Customers Affected: N/A

Main Size: 2" Repaired Under Pressure: YES ✓ NO ____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) / NO

¹Time Water Main Valved Off (positive pressure removed): N/A am / pm

Nature of Leak or Break:

Replaced service line

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES) (NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: _____ Minutes

Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ____ NO ____

(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

COPY