FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-19-13 Time: Location: 328 Baumsmore	
Please Circle Appropriate Action: New Line Installation / Line Repair (Service)	
NEW LINE INSTALLATION:	COP
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if ne	eded):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:	
Water Supply (WS) Project Number:	
FOR LINE REPAIRS:	
Interruption of Water Service: YES NONumber of CustomersAf	ffected:
Main Size: 6" PVC Repaired Under Pressure: YES V NO	
For partially or fully de-watered mains:	9
Was positive pressure maintained while a trench was opened and area on NO) Time Water Main Valved Off (positive pressure removed):	
Nature of Leak or Break: Aroke Service line changed out service	
Were State approved or AWWA Standards Followed: (YES)/ NO) Detailed summary of repair procedure used (Use back of page if needed	() :
Was water main contaminated during the repair process? (YES /NO) Disinfection Procedure / Calculations (Use back of page if needed):	
Amount of Time Line Flushed: Minutes Ending Chi Residual: mg/L	lorine
Bacteriological Sample Collected: YES NO Results**:_ (**Attach copy of results to record)	
Date / Time Water Main Returned to Service:	am / pm
Additional Comments:	

Rev 01-21-09

