

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-7-11 Time: 10:45 Am Location: 342 Mangrove St

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

Date Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date Time Water Main Returned to Service: 20

am pm

Additional Comments:

