FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 5-4-10 Time: 9:30 Fim. Location: 428 Hillside. Dr.
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" Gilo Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm Nature of Leak or Break:
Split in top of 2" Galuc
Were State approved or AWWA Standards Followed (YES) NO) Detailed summary of repair procedure used (Use back of page if needed): Repailed with bank
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Rev 01-21-09 2x3' 40(c) 90 sec to ssise 6"
10 sec to laise 6

Y900

.