## FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-2-14 Time: All Day Location: 547 Airport Rd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:  Were State approved or AWWA Standards Followed: (YES / NO)  Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial  Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 6" PUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)  Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: leaking plastic Service
Were State approved or AWWA Standards Followed: (YES) NO)  Peplaced With  Detailed summary of repair procedure used (Use back of page if needed): Copper + Pcx
Was water main contaminated during the repair process? (YES / NO)  Plusted line  Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results***  (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sce Photos
286 07-27-09 \$ 56 PSi Defore 11 GPM AFER Don'e T.S.

- A - A