

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 3-9-12 Time: 11:45 Location: 703 Clifty St

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

**NEW LINE INSTALLATION:**

**COPY**

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

3-16-12  
J

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

**FOR LINE REPAIRS:**

Interruption of Water Service: YES  NO  Number of Customers Affected: 1

Main Size: 8" cast Repaired Under Pressure: YES  NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed) \_\_\_\_\_ am / pm

Nature of Leak or Break: leaking service

Were State approved or AWWA Standards Followed: (YES / NO) Replaced with  
Detailed summary of repair procedure used (Use back of page if needed): COPPER

Was water main contaminated during the repair process? (YES / NO) Flushed Line  
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed 1 Minutes  
Residual \_\_\_\_\_ mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES  NO   
(\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments: See Photos

Adam-Billy-Bull

5 GPM Leak

COPY