FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR



Date: 7-23-13 Time: 10:45 Location: \$12 Hessler Mill 7-34
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 4" PUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) 1 Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: eaking plastic Service
Were State approved or AWWA Standards Followed: (YES) NO) Replaced with Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Flus hed line Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: See Photo
Rev 01-21-09 Donnic - Adam

Jimry - TJ.

V900

in the value of the angle of the same

in the second se

0.8 - 55

8 7

grand a

greening and special to a con-

E frys i e

F 19

and the second s