

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-30-10 Time: 12:00 p.m. Location: 959 Renkin Chapel Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size 4" PVC

Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO

Time Water Main Valved Off (positive pressure removed):

am pm

Nature of Leak or Break:

hole in bottom of 4" PVC

Were State approved or AWWA Standards Followed: (YES) NO

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? (YES) (NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached band

Amount of Time Line Flushed: Minutes

Ending Chlorine

Residual mg/L

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date Time Water Main Returned to Service: 20

am / pm

Additional Comments:

Good leak

20 + GPM

Adam Kim
Billy

