

Date: 11-16-10

Time: 9:30 a.m.

Location: Airport Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were state approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO ✓ Number of Customers Affected:

Pipe Size: 6" PVC Repaired Under Pressure: YES NO

Was partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES) (NO)

Water Main Valved Off (positive pressure removed): am pm

Location of Leak or Break:

hole in side of 6" PVC water main

Were State approved or AWWA Standards Followed: (YES) (NO)

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with Band

Was water main contaminated during the repair process? (YES) (NO)

Disinfection Procedure: Calculations (Use back of page if needed):

Bleached Band

Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L

Bacteriological Sample Collected: YES NO Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments:

10+ GPM Leak

See Photos

Adam-Bull-Billy

