

1 day long, 15.71ly, 1 km, 15.71m

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 7-26-6 Time: 10:49 AM Location: Airport Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush _____ Chlorine Residual after Flush: _____

COPY

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES _____ NO ☒ Number of Customers Affected _____

Main Size 6" PVC Repaired Under Pressure: YES ☒ NO _____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Pin hole in pipe

Were State approved or AWWA Standards Followed (YES / NO) YES

Detailed summary of repair procedure used (Use back of page if needed):

cleaned pipe & band & dug 16" below & around pipe

Was water main contaminated during the repair process? (YES / NO) NO

Disinfection Procedure / Calculations (Use back of page if needed):

cleaned parts & material with Bleach

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES _____ NO _____ Results** _____
(* Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

