FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
ate: 9-8-09 Time: 10:00 a.r. Location: A. Sport Rd
lease Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR
IEW LINE INSTALLATION:
Vere State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Date / Time of Initial Flush: Chlorine Residual after Flush:
Nater Supply (WS) Project Number:
FOR LINE REPAIRS:
nterruption of Water Service: YES NONumber of Customers Affected:
Main Size: Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)
Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Customer hit Service line w/ truckler
Were State approved or AWWA Standards Followed: (YESINO) Detailed summary of repair procedure used (Use back of page if needed): Repaired 4' section with comp union and curb stop
Was water main contaminated during the repair process? (YES /NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:
Date / Time Water Main Returned to Service: 20 am / pm
Additional Comments:
60 sec to raise 6" 2'X3' hole

지미아유