

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

COPY

Date: 9-12-11 Time: 3pm Location: Alley behind Terry Duncan FordPlease Circle Appropriate Action: New Line Installation Line Repair / Service LineTaylor, Reed, Clark

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 1Main Size: 2" Poly Repaired Under Pressure: YES ☐ NO ☒For partially or fully de-watered mains:Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO)Time Water Main Valved Off (positive pressure removed): 2:00 am / pm

Nature of Leak or Break:

Fuse broke downWere State approved or AWWA Standards Followed: (YES) NO)

Detailed summary of repair procedure used (Use back of page if needed):

dig around & below line & cleared areaWas water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

cleaned material & pipe with bleach & installed parts.

Amount of Time Line Flushed: _____ Minutes

Ending Chlorine

Residual: _____ mg/L

Bacteriological Sample Collected: YES ☐ NO ☐

Results**: _____

(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

COPY