

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

12-1-10 Time: 2:00 p.m. Location Bullfield + Day Rd

Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were state approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

Date Time of Initial Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES NO Number of Customers Affected

2" PVC Repaired Under Pressure YES NO

Was partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? YES

Water Main Vaived Off (positive pressure removed) am pm

Location of Leak or Break Split in side of 2" PVC

Were State approved or AWWA Standards Followed: (YES) NO
Detailed summary of repair procedure used (Use back of page if needed)

Repaired with band

Was water main contaminated during the repair process? (YES) NO
Disinfection Procedure Calculations (Use back of page if needed)

Bleached Band

Amount of Time Line Flushed Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected YES NO Results**
**Attach copy of results to record)

Date Time Water Main Returned to Service 20 am pm

Additional Comments

See Photos

Adam-Tim-Bull-Reed

