

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-31-14 Time: 2:00 Location: Barnett Circle

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of disinfection procedure used (Use back of page if needed):

**COPY**

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

**FOR LINE REPAIRS:**

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 1

Main Size: 2" plastic Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) / NO

<sup>1</sup>Time Water Main Valved Off (positive pressure removed): 2:30 am / pm

Nature of Leak or Break:

Fuse leaking

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: \_\_\_\_\_ Minutes  
Residual: \_\_\_\_\_ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐  
(\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: 1-31-14 3:30 am / pm

Additional Comments:

...

GOBA

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...