	FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
	Date: 3-5-14 Time: -2:30 Location: Barel Rol Hennich
	Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
	NEW LINE INSTALLATION:
÷	Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
	Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
	Water Supply (WS) Project Number:
	FOR LINE REPAIRS:
•	Interruption of Water Service: YES NONumber of CustomersAffected:
	Main Size: 2 PUC Repaired Under Pressure: YES NO
	For partially or fully de-watered mains:
J	Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)
	¹ Time Water Main Valved Off (positive pressure removed): am / pm
	Nature of Leak or Break: De Leaking Service linc
	Were State approved or AWWA Standards Followed: (YESINO) Killed Service Detailed summary of repair procedure used (Use back of page if needed): $c_1 + f_{ap}$
	Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
	Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
	Bacteriological Sample Collected: YESNO Results**:
	Date / Time Water Main Returned to Service:am / pm
	Additional Comments: Cut corporation off and capped
	Adem Scc Photos Vacent tap
	Billy



역에 가지 않는 것을 가려면 가려져 가운 바람은 가지 않는 것을 가지 않는 것이다. 가지 않는 것을 가지 않는 것이다. 2019년 1월 2019

an β a ha Protectaria an Ilana an Nationa an Protectaria an Ilana a