

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-21-11 Time: 3:00p Location: Berkshire Ln

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)  
Detailed summary of disinfection procedure used (Use back of page if needed)

Jeff, Ada  
Drew  
Kim

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

COPY

## FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected 1

1-24-11  
J

Main Size 2" poly Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) ☒ (NO) ☐

Time Water Main Valved Off (positive pressure removed): 2:30 am (pm) ☒

Nature of Leak or Break:

Tied line into New 6" PVC @ Valve

Were State approved or AWWA Standards Followed: (YES) ☒ (NO) ☐  
Detailed summary of repair procedure used (Use back of page if needed):

Electro Fused 2" poly

Was water main contaminated during the repair process? (YES) ☐ (NO) ☒  
Disinfection Procedure / Calculations (Use back of page if needed):

Bleached All Parts & Pipe

Amount of Time Line Flushed: 30 Minutes  
Residual mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES ☐ NO ☐

Results\*\*

\*\*Attach copy of results to record)

Date: Time Water Main Returned to Service: 20

am: pm

Additional Comments:

COBOL