FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date 7-311 Time: 2:30Am Location: Big Johns N. Lone SL.
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO)
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NO / Number of CustomersAffected
Main Size: 2 Gale Repaired Under Pressure: YES NO Pantial
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES/ NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Hole in pipe.
Were State approved or AWWA Standards Followed: (FES) NO) Detailed summary of repair procedure used (Use back of page if needed): Dry belan + around Pipe + cleaned.
Was water main contaminated during the repair process? (YES (NO)) Disinfection Procedure / Calculations (Use back of page if needed): Cleaned parts & material with Bleach
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

Rev 01-21-09

길이는