

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 3-19-13 Time: 6:00 PM Location: Harriman Hwy / Boswell Chapel

Please Circle Appropriate Action: New Line Installation Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 25

Main Size: 6" PVC Repaired Under Pressure: YES ☒ NO ☐

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break

split in 6" main

Were State approved or AWWA Standards Followed (YES / NO) Replaced 8ft section
Detailed summary of repair procedure used (Use back of page if needed): with knock-ons

Was water main contaminated during the repair process? (YES / NO) Bleached pipe &
Disinfection Procedure / Calculations (Use back of page if needed): Knock-ons

Amount of Time Line Flushed: _____ Minutes
Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐
(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: See Photos

Donnie - Billy - Adam - Tim

COPY