

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1/19/10 Time: 10:00 AM Location: Circle Dr.

Please Circle Appropriate Action: New Line Installation Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

1-25-10

8

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ____ NO ☒ Number of Customers Affected: None

Main Size: 2" Repaired Under Pressure: YES ☒ NO ____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ☒

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

2" Coupling installed 2" / 5" Band

Were State approved or AWWA Standards Followed: (YES / NO) ☒

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO) ☒

Disinfection Procedure / Calculations (Use back of page if needed):

Bleach Band before installing and galvanized line

Amount of Time Line Flushed: _____ Minutes

Ending Chlorine

Residual: _____ mg/L

Bacteriological Sample Collected: YES ____ NO ____

Results**: _____

(**Attach copy of results to record)

Date / Time Water Main Returned to Service: 1/19/10 11:00 am / pm

Additional Comments:

2' x 4' pipe 6" 20 sec.

1-2-3