

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: ¹⁰2-11-11 Time: 10:00 a.m. Location: Clifty Creek Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

2-11-11
J

Date / Time of Initial Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES _____ NO ☒ Number of Customers Affected: _____

Main Size: 4" PVC Repaired Under Pressure: YES _____ NO _____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ☒

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

small hole in bottom of main

Were State approved or AWWA Standards Followed: (YES / NO) ☒

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? (YES / NO) ☒

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached Band

Amount of Time Line Flushed: _____ Minutes
Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES _____ NO _____
(**Attach copy of results to record)

Results**:

Date / Time Water Main Returned to Service: _____ 20 _____ am / pm

Additional Comments: See Photos

Adam-Daniel-Kim

Handwritten text, possibly a signature or date, located in the upper left corner.