

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-21-10 Time: 10:30 am Location: Clifty St

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected: 0

Main Size: 6" cast Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Killed out 2 - 3/4 taps - one was leaking

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Unscrewed both taps out of main and put band over both

Was water main contaminated during the repair process? (YES / NO) Bleached Band  
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes  
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO  
\*\*Attach copy of results to record)

Results\*\*

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments:

See Photos

