

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 7-21-10 Time 12:00 p.m. Location Cumberland & Queen

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush _____

Date / Time of Initial Flush _____ Length of Time of Initial

Flush _____ Chlorine Residual after Flush _____

Water Supply (WS) Project Number _____

FOR LINE REPAIRS:

Interruption of Water Service YES ☒ NO ☐ Number of Customers Affected 1

Main Size 2" Poly Repaired Under Pressure YES ☐ NO ☒

For partially or fully de-watered mains.

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed) _____ am / pm

Nature of Leak or Break

Replace section of poly - leaking at a fuse

Were State approved or AWWA Standards Followed: (~~YES~~ / NO)

Detailed summary of repair procedure used (Use back of page if needed)

Replaced with brass pipes, and electrofuse couplings

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed)

Flushed line - Bleached Brass

Amount of Time Line Flushed 2 Minutes

Ending Chlorine 2.20

Residual _____ mg/L

Bacteriological Sample Collected: YES ☐ NO ☐

Results** _____

(**Attach copy of results to record)

Date / Time Water Main Returned to Service _____ am / pm

Additional Comments

YF00