

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 11-4-09 Time 11:00am Location Day Rd

Please Circle Appropriate Action: New Line Installation Line Repair Service Line

COPY
Jr 11/5/09

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush Length of Time of Initial Flush
Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES ☒ NO ☐ Number of Customers Affected 8

Main Size 2" Repaired Under Pressure YES ☐ NO ☒

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES) ☒ NO ☐

Time Water Main Valved Off (positive pressure removed) 10:30 am pm

Nature of Leak or Break

Installing a 1" PRU

Were State approved or AWWA Standards Followed (YES / NO) YES

Detailed summary of repair procedure used (Use back of page if needed)

Repaired with Gelo Dressers, Brass nipples, PRU

Was water main contaminated during the repair process? (YES) NO

Disinfection Procedure / Calculations (Use back of page if needed)

Bleached pipe & Dressers - Flushed line

Amount of Time Line Flushed 30 Minutes
Residual 2.20 mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected YES ☐ NO ☐

Results**

**Attach copy of results to record

Date Time Water Main Returned to Service: am pm

Additional Comments

checked Russ Oren's meter 52 psi / 17 GPM / 2.20 cl²

