FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

ate 2-7-12 Time: 10:30 Location: Day Rd
Please Circle Appropriate Action: New Line Installation/ Line Repair / Service Line
NEW LINE INSTALLATION:
Nere State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" DUC Repaired Under Pressure: YES NO
For partially or fully de watered mains:
Was positive pressure maintained while a trench was opened and area cleaned (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Split in 2" PUC main
Were State approved or AWWA Standards Followed: (YES/NO) Repoired with Detailed summary of repair procedure used (Use back of page if needed): Bend
Was water main contaminated during the repair process? (YES (NO) Bleached Bend Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: See Photos Adam - Bull - Toby
15 GPM Leak 11

