FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

FIELD DATA ON NELTY LINE MOTHER THON ON THE THE
Date: 11-25-14 Time: 9400 Am. 11:30 Am. Location: Devonia St.
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: / Galv. Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Sorros, on Hole.
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO) Disinfection Procedure / Calculations (Use back of page if needed): Bleacher Bant.
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

COPY