

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 10-29-10 Time: 11:00 a.m. Location: Dogwood Ct + Pine Ridge Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
 Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

Time of Initial Flush

Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES NO Number of Customers Affected

Repaired Under Pressure YES NO

partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES)

Water Main Valved Off (positive pressure removed): 11:30 am pm

Leak or Break

leak at fuse on 2" Poly main

Were State approved or AWWA Standards Followed (YES) NO

Detailed summary of repair procedure used (Use back of page if needed):

Replace 7ft section of main from 2" valve to 90° Bend

Was water main contaminated during the repair process? (YES) NO

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached / Sucked pipe, fittings, Flushed line

Amount of Time Line Flushed: 30
 Residual mg/L

Minutes

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date Time Water Main Returned to Service

20

am pm

Additional Comments

Good leak

10+ GPM

Y-2650