

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9/8/10 Time: 12:30 - 7:30 Location: Duff's Pump Station

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date: Time of Initial Flush: Chlorine Residual after Flush

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected 0

Main Size 4" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): 5:00 am pm

Nature of Leak or Break:

Line was hit by Contractors Digging for Storm Drain.

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Proper PPE, and disinfectants were used

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Breach was put in piece of pipe that was replaced

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results**

(** Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments:

Adam, Billy, Kim

