FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 4-2-12 Time: 4:30 Location: Emory St
Please Circle Appropriate Action: New Line Installation Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): 4-3-12-3-12-3-12-3-12-3-12-3-12-3-12-3-1
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 4" cast Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Split in 4" cast main
Were State approved or AWWA Standards Followed: (YES / NO) Repaired with Detailed summary of repair procedure used (Use back of page if needed): 30" Band
Was water main contaminated during the repair process? (YES / NO) Bleached Bond Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: See Photos
Bad Leak Billy Deniel

COPY