FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 5-14-13 Time: Location: Edergreen
Please Circle Appropriate Action: New Line Installation Line Repair Service Line
NEW LINE INSTALLATION: 5/20/13
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 3/A +CANS Repaired Under Pressure: YES NO
For partially or fully de-watered mains
Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO) Time Water Main Valved Off (positive pressure removed):/A am / pm
Nature of Leak or Break Snodle move tap to 8 in CAST
Were State approved or AWWA Standards Followed: (YES) NO) Detailed summary of repair procedure used (Use back of page if needed): 16 inches Around Pipe bleached band
Was water main contaminated during the repair process? (YES NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: ***Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

Rev 01-31-09

