FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-23-16 Time: 10:00 414 Location: Fiske Kd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush:Length of Time of Initial Flush:Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: 2 holes in 1' Gilu
Were State approved or AWWA Standards Followed: (YES INO) Detailed summary of repair procedure used (Use back of page if needed): Repaired both holes with IX6' Band Was water main contaminated during the repair process? (YES NO)
Disinfection Procedure / Calculations (Use back of page if fleeded).
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

Rev 01-21-09

v '€n€s