FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 6-5-10 Time 2:30 P.M. Location: Forest Hills Dr.
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Elush: Chlorine Residual after Flush: Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service. YES NONumber of CustomersAffected
Main Size: 2" PUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned (YES NO) Time Water Main Valved Off (positive pressure removed): am / pm Nature of Leak or Break:
Were State approved or AWWA Standards Followed (YES)NO) Detailed summary of repair procedure used (Use back of page if needed): Split Repaired with Bend Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed): Bleached bend
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results** (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: 2'x3'
Additional Comments: 2'x3'

60 sect to raise 6"

Y900