

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-17-11 Time: 2:00 p Location: Fred Davis Jr

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

*Bobby Mayse
Const, Jett*

Date Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

COPY

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 10

Main Size: 2" Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): 1:50 am pm

Nature of Leak or Break:

2" line Tied line over to 6" DI

Were State approved or AWWA Standards Followed: YES / NO

Detailed summary of repair procedure used (Use back of page if needed):

Tied 2" into Existing Valve off 6" D.I Bleached All Parts

Was water main contaminated during the repair process? (YES / NO) NO

Disinfection Procedure / Calculations (Use back of page if needed)

Bleach Fittings & Pipe

Amount of Time Line Flushed: 45 Minutes
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐

Results**

**Attach copy of results to record)

Date - Time Water Main Returned to Service: 20

am / pm

Additional Comments:

