

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

COPY

Date: 12-4-14 Time: 10:00 Location: Acme Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ✓ Number of Customers Affected: 0

Main Size: 2" PVC Repaired Under Pressure: YES ✓ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: hit with Backhoe

Were State approved or AWWA Standards Followed: YES / NO) Replace 2ft

Detailed summary of repair procedure used (Use back of page if needed): With Knock-on

Was water main contaminated during the repair process? (YES / NO) NO Black pipe and Knock-on

Amount of Time Line Flushed: _____ Minutes Ending Chlorine Residual: _____ mg/L

Bacteriological Sample Collected: YES ___ NO ___ Results**: _____
(*Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: See Photos

Taylor Adam Billy Jimmy

COPY