

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 7-24-10 Time 8:00 am Location: Hannah Rd

Please Circle Appropriate Action: New Line Installation Line Repair / Service Line

COPY

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of disinfection procedure used (Use back of page if needed):

used chlorine to clean pipe

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: 7-24 Length of Time of Initial

Flush: fire hydrant Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ✓ NO _____ Number of Customers Affected 6 est

Main Size: 4" PVC Repaired Under Pressure: YES ✓ NO ~~✓~~
throttled down

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)

Time Water Main Valved Off (positive pressure removed): 10:00 am / pm

Nature of Leak or Break:

2nd crack in line

Were State approved or AWWA Standards Followed: (YES) / NO

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: 30 Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES _____ NO ✓ Results** _____
(*Attach copy of results to record)

Date / Time Water Main Returned to Service: 7-24-10 10:30 am / pm

Additional Comments:

water flowing out both ends of pipe.

COPY