

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8-6-10 Time: 1:00pm Location: Hwy 299 mile Marker 6

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

8-9-10
J

Date / Time of Initial Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES _____ NO ✓ Number of Customers Affected: _____

Main Size: 6" PVC Repaired Under Pressure: YES ✓ NO _____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO) _____

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: pin hole in 6" PVC water main

Were State approved or AWWA Standards Followed: (YES) / NO) _____

Detailed summary of repair procedure used (Use back of page if needed):

Bleached band

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: _____ Minutes

Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES _____ NO _____

(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ 20 _____ am / pm

Additional Comments:

Bleached band

COPY