MANINE/ King
FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date: 1-13-10 Time: 6 00 Pm Location: Jasper Street
Date: 1-13-10 Time: 6 00 Pm Location: Jasper Street
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NO Number of CustomersAffected:
Main Size: Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YESA NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break:
Were State approved or AWWA Standards Followed: (YES, NO) Detailed summary of repair procedure used (Use back of page if needed): Put bleech on band & Cleaned Pipe
Was water main contaminated during the repair process? (YES (NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: 18" X 2 40000 + f:ll 6"
Rev. 01-21-09 90 Sec.

