

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 7/22/11 Time: 2:00 P.m. Location: Menth Circle Pump Station ^{below}

Please Circle Appropriate Action: New Line Installation ☒ Line Repair / Service Line

COPY

7/27/11

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ☒ Number of Customers Affected None

Main Size: 2" Repaired Under Pressure: YES ☒ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ☒

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Coupling leaking 2" galv

Were State approved or AWWA Standards Followed: (YES / NO) ☒

Detailed summary of repair procedure used (Use back of page if needed):

bleach on hand

Was water main contaminated during the repair process? (YES / NO) ☒

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: _____ Minutes
Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ___ NO ___
(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

581,645

COPY