FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date 3-2-10 Time: 9:00 9, r. Location: Old Airport Rd
Please Circle Appropriate Action: New Line Installation / Line Repair Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): $\mathcal{F}^{3-\delta-1,0}$
Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected: Main Size: Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Pig hole in 2" PUC
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed): Repaired with 2×6' FLU Circle Band Was water main contaminated during the repair process? (YES (NO)) Disinfection Procedure / Calculations (Use back of page if needed): Blescled Band
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

0.1	(11-2	01-21-

 $\sim 1 {\rm km} \lambda$