

37

## FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-28-14 Time: 10 Am Location: Pine Orchard Rd  
 Please Circle Appropriate Action: New Line Installation Line Repair Service Line By Pine Orchard Church

## NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed): 2-5-148

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: \_\_\_\_\_

Main Size: 4" PUC Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break:

4x2 puc insect broke

Were State approved or AWWA Standards Followed: (YES) NO

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: \_\_\_\_\_ Minutes  
 Residual: \_\_\_\_\_ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐  
 (\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments:

Adam, Donnie, Taylor, Jimmy, TJ

COPY