

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-1-12 Time: 10:00 am Location: Pine Ridge & Ruliten

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 4

Main Size: 2" Poly Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Truck ran over Valve - Broke Butt Flx

Were State approved or AWWA Standards Followed (YES / NO) NO Replaced Valve and
Detailed summary of repair procedure used (Use back of page if needed):
Broken section

Was water main contaminated during the repair process? (YES / NO) NO Bleached Pipe
Disinfection Procedure / Calculations (Use back of page if needed):
Fittings
Flushed line

Amount of Time Line Flushed: 5 Minutes

Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☐

(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: See Photos

Adam - Tim - Dannie - Jimmy

COPY