

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

11-1-10

Time: 7pm

Location: Powers Loop

Please Circle Appropriate Action: NEW LINE INSTALLATION LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Time of Initial Flush

Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Disruption of Water Service: YES NO Number of Customers Affected

Pipe Size: 4" PVC

Repaired Under Pressure: YES

NO partial pressureWas partially or fully de-watered mainsWas positive pressure maintained while a trench was opened and area cleaned? YES

at

Water Main Valved Off (positive pressure removed): 7:00 am pm

Location of Leak or Break

Crack in pipe

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Dug below pipe & cleaned pipe.

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure - Calculations (Use back of page if needed)

Cleaned material & pipe with bleach & installed in service

Amount of Time Line Flushed
Residual mg/L

Minutes

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date Time Water Main Returned to Service

20

am pm

Additional Comments

